

which consumers can reasonably be expected to use that would harm the product or others being washed with it in one or more washings, the label must contain a warning to this effect. The warning must use words “Do not,” “No,” “Only,” or some other clear wording. [For example, if a shirt is not colorfast, its label should state “Wash with like colors” or “Wash separately.” If a pair of pants will be harmed by ironing, its label should state “Do not iron.”]

(B) Warnings are not necessary for any procedure that is an alternative to the procedure prescribed on the label. [For example, if an instruction states “Dry flat,” it is not necessary to give the warning “Do not tumble dry.”]

(2) *Drycleaning*—(i) *General*. If a drycleaning instruction is included on the label, it must also state at least one type of solvent that may be used. However, if all commercially available types of solvent can be used, the label need not mention any types of solvent. The terms “Drycleanable” or “Commercially Dryclean” may not be used in an instruction. [For example, if drycleaning in perchlorethylene would harm a coat, the label might say “Professionally dryclean: fluorocarbon or petroleum.”]

(ii) *Warnings*. (A) If there is any part of the drycleaning procedure which consumers or drycleaners can reasonably be expected to use that would harm the product or others being cleaned with it, the label must contain a warning to this effect. The warning must use the words “Do not,” “No,” “Only,” or some other clear wording. [For example, the drycleaning process normally includes moisture addition to solvent up to 75% relative humidity, hot tumble drying up to 160 degrees F and restoration by steam press or steam-air finish. If a product can be drycleaned in all solvents but steam should not be used, its label should state “Professionally dryclean. No steam.”]

(B) Warnings are not necessary to any procedure which is an alternative to the procedure prescribed on the label. [For example, if an instruction states “Professionally dryclean, fluorocarbon,” it is not necessary to give the

warning “Do not use perchlorethylene.”]

(c) A manufacturer or importer must establish a reasonable basis for care information by processing prior to sale:

(1) Reliable evidence that the product was not harmed when cleaned reasonably often according to the instructions on the label, including instructions when silence has a meaning. [For example, if a shirt is labeled “Machine wash. Tumble dry. Cool iron,” the manufacturer or importer must have reliable proof that the shirt is not harmed when cleaned by machine washing (in hot water), with any type of bleach, tumble dried (at a high setting), and ironed with a cool iron]; or

(2) Reliable evidence that the product or a fair sample of the product was harmed when cleaned by methods warned against on the label. However, the manufacturer or importer need not have proof of harm when silence does not constitute a warning. [For example, if a shirt is labeled “Machine wash warm. Tumble dry medium”, the manufacturer need not have proof that the shirt would be harmed if washed in hot water or dried on high setting]; or

(3) Reliable evidence, like that described in paragraph (c)(1) or (2) of this section, for each component part of the product in conjunction with reliable evidence for the garment as a whole; or

(4) Reliable evidence that the product or a fair sample of the product was successfully tested. The tests may simulate the care suggested or warned against on the label; or

(5) Reliable evidence of current technical literature, past experience, or the industry expertise supporting the care information on the label; or

(6) Other reliable evidence.

[48 FR 22743, May 20, 1983; 48 FR 24869, June 3, 1983, as amended at 65 FR 47275, Aug. 2, 2000]

§ 423.7 Certain piece goods.

This section applies to certain piece goods.

(a) Manufacturers and importers of certain piece goods must provide care information clearly and conspicuously on the end of each bolt or roll.

(b) Care information must say what regular care is needed for the ordinary

use of the product, pursuant to the instructions set forth in § 423.6. Care information on the end of the bolt need only address information applicable to the fabric.

§ 423.8 Exemptions.

(a) Any item of textile wearing apparel, without pockets, that is totally reversible (i.e., the product is designed to be used with either side as the outer part or face) is exempt from the care label requirement.

(b) Manufacturers or importers can ask for an exemption from the care label requirement for any other textile wearing apparel product or product line, if the label would harm the appearance or usefulness of the product. The request must be made in writing to the Secretary of the Commission. The request must be accompanied by a labeled sample of the product and a full statement explaining why the request should be granted.

(c) If an item is exempt from care labeling under paragraph (a) or (b), of this section the consumers still must be given the required care information for the product. However, the care information can be put on a hang tag, on the package, or in some other conspicuous place, so that consumers will be able to see the care information before buying the product.

(d) Manufacturers and importers of products covered by § 423.5 are exempt from the requirement for a permanent care label if the product can be cleaned safely under the harshest procedures. This exemption is available only if there is reliable proof that all of the following washing and drycleaning procedures can safely be used on a product:

- (1) Machine washing in hot water;
- (2) Machine drying at a high setting;
- (3) Ironing at a hot setting;
- (4) Bleaching with all commercially available bleaches;
- (5) Drycleaning with all commercially available solvents. In such case, the statement "wash or dry clean, any normal method" must appear on a hang tag, on the package, or in some other conspicuous place, so that consumers will be able to see the statement before buying the product.

If a product meets the requirements outlined above, it is automatically exempt from the care label requirement. It is not necessary to file a request for this exemption.

(e) Manufacturers and importers need not provide care information with products sold to institutional buyers for commercial use.

(f) All exemption granted under § 423.1(c) (1) or (2) or the Care Labeling Rule issued on December 9, 1971, will continue to be in effect if the product still meets the standards on which the original exemption was based. Otherwise, the exemption is automatically revoked.

(g) The symbol system developed by the American Society for Testing and Materials (ASTM) and designated as ASTM Standard D5489-96c Guide to Care Symbols for Care Instructions on Consumer Textile Products may be used on care labels or care instructions in lieu of terms so long as the symbols fulfill the requirements of this part. In addition, symbols from the symbol system designated as ASTM Standard D5489-96c may be combined with terms so long as the symbols and terms used fulfill the requirements of this part. Provided, however, that for the 18-month period beginning on July 1, 1997, such symbols may be used on care labels in lieu of terms only if an explanation of the meaning of the symbols used on the care label in terms is attached to, or provided with, the item of textile wearing apparel. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies of ASTM Standard D5489-96c Guide to Care Symbols for Care Instructions on Textile Products may be obtained from the American Society for Testing and Materials, 100 Barr Harbor Drive, West Conshohocken, PA 19428, or may be inspected at the Federal Trade Commission, room 130, 600 Pennsylvania Avenue, NW., Washington, DC, or at the Office of the Federal Register, suite 700, 800 North Capitol Street, NW., Washington, DC.

(15 U.S.C. 41-58)

[48 FR 22743, May 20, 1983; 48 FR 24869, June 3, 1983; 62 FR 29008, May 29, 1997]